




## Réparation

### Coins pour réparation

Paquets de 96




		1 à 5	6 à 11	12 à 23	24+
Transparent	<b>BRPL-COP12000</b>	<b>9,79\$</b>	<b>9,71\$</b>	<b>9,62\$</b>	<b>9,54\$</b>
Toile brune	<b>BRPL-COP2001BR</b>	<b>15,89\$</b>	<b>15,00\$</b>	<b>14,20\$</b>	<b>13,42\$</b>
Toile bleue	<b>BRPL-COP2001BL</b>	<b>15,89\$</b>	<b>15,00\$</b>	<b>14,20\$</b>	<b>13,42\$</b>
Toile rouge	<b>BRPL-COP2001R</b>	<b>15,89\$</b>	<b>15,00\$</b>	<b>14,20\$</b>	<b>13,42\$</b>
Toile noire	<b>BRPL-COP2001N</b>	<b>15,89\$</b>	<b>15,00\$</b>	<b>14,20\$</b>	<b>13,42\$</b>
Toile verte	<b>BRPL-COP2001V</b>	<b>15,89\$</b>	<b>15,00\$</b>	<b>14,20\$</b>	<b>13,42\$</b>

### Ailerons pour réparation

Paquets de 24

		1 à 5	6 à 11	12 à 23	24+
Transparent	<b>BRPL-AIP12000</b>	<b>6,69\$</b>	<b>6,31\$</b>	<b>6,00\$</b>	<b>5,62\$</b>
Toile brune	<b>BRPL-AIP2001BR</b>	<b>10,09\$</b>	<b>9,63\$</b>	<b>9,11\$</b>	<b>8,57\$</b>
Toile bleue	<b>BRPL-AIP2001BL</b>	<b>10,09\$</b>	<b>9,63\$</b>	<b>9,11\$</b>	<b>8,57\$</b>
Toile rouge	<b>BRPL-AIP2001R</b>	<b>10,09\$</b>	<b>9,63\$</b>	<b>9,11\$</b>	<b>8,57\$</b>
Toile noire	<b>BRPL-AIP2001N</b>	<b>10,09\$</b>	<b>9,63\$</b>	<b>9,11\$</b>	<b>8,57\$</b>
Toile verte	<b>BRPL-AIP2001V</b>	<b>10,09\$</b>	<b>9,63\$</b>	<b>9,11\$</b>	<b>8,57\$</b>



### Renforts de revues Easy Hold

Paquet de 250

**43,00\$**

8,26 cm (3¼")

**BRPL-HP1001**